

Appraisal Information

Description of Condition:

Condition Number One: This describes a vehicle that has had a recent, quality and proper restoration to a like-new condition.

Condition Number Two: This describes a vehicle that has had an older complete restoration showing some signs of use or wear, an excellent original unrestored vehicle, or a vehicle that has undergone a recent restoration but is still in need of some completion.

Condition Number Three: This describes a vehicle that is in good condition, presentable, sound, complete, and drivable.

Condition Number Four: This describes a vehicle that is complete but in poor condition and in need of restoration work.

Condition Number Five: This describes a vehicle that is in very poor condition with structural problems and is in an incomplete state (not running or drivable.)

Vehicle Condition Report

1970 Lincoln Mark III: Maroon metallic, 460 V-8 automatic, A/C, power steering, power brakes, cruise control, white interior, white vinyl roof. Condition – 2

1978 Cadillac Seville: Leather tan interior, original paint, V-8 350 ci, fuel injected automatic, factory A/C, air ride suspension, tilt wheel, power seats, cruise control, wire wheel hubcaps. Condition – 2

1960 Ford T-bird: Turquoise, solid and rust free, matching two tone interior, V-8, automatic transmission, power steering, power steering, power windows, bucket seats, A/C. Condition – 3

1967 Mercury Cougar XR7: Yellow exterior with white painted hardtop, solid original body, white interior, 289 cu V-8 engine, automatic transmission, power steering, A/C, tilt wheel. Condition – 3

1977 Lincoln Continental Mark V: White exterior and ½ vinyl roof, white leather interior with blue dash and carpeting, V-8 engine, automatic transmission, power steering, power brakes, power windows, power seats, power sun-roof, AM/FM stereo, factory aluminum mag wheels. Condition – 2-3

1985 Mercedes 380 SL Roadster: Silver blue exterior, European headlights, automatic A/C, power steering, power brakes, power windows, chrome mag wheels, factory hardtop. Condition – 3

1967 Ford T-bird: Turquoise metallic with matching interior, bucket seats, console, V-8 engine, power steering, power brakes. Condition – 3

1966 Chevrolet Corvair Coupe: White, automatic transmission, A/C, AM/FM radio. Condition – 4-5